

This report provided free of charge by:

Imports Collection Inc. 1861 NW 97th Ave, Doral, FL 33172

(305) 597-4332



Vehicle History Report[™]

US \$39.99

2004 MERCEDES-BENZ E 320 4MATIC

VIN: WDBUH82J74X115138 WAGON 4 DR 3.2L V6 F SOHC 18V GASOLINE ALL WHEEL DRIVE

This CARFAX Report Provided by:

Imports Collection Inc.



No accidents or damage reported to CARFAX



2 Previous owners



At least 1 open recall



22 Service history records



Types of owners: Lease, Personal



77,651 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/29/21 at 2:28:05 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Ownership History The number of owners is estimated	a Owner 1	🚨 Owner 2
Year purchased	2003	2009
Type of owner	Lease	Personal
Estimated length of ownership	5 years	12 yrs. 3 mo.
Owned in the following states/provinces	Connecticut	Connecticut
Estimated miles driven per year	7,481/yr	3,847/yr
Last reported odometer reading	37,611	77,651

CARFAX Title History CARFAX guarantees the information in this section	🚨 Owner 1	🚨 Owner 2
Salvage Junk Rebuilt Fire Flood Hail Lemon	Guaranteed No Problem	Guaranteed No Problem
Not Actual Mileage Exceeds Mechanical Limits	Guaranteed No Problem	Guaranteed No Problem



GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back.

Register | View Terms | View Certificate

CARFAX Additional History Not all accidents / issues are reported to CARFAX	A Owner 1	🚨 Owner 2
Total Loss No total loss reported to CARFAX.	No Issues Reported	No Issues Reported
Structural Damage No structural damage reported to CARFAX.	No Issues Reported	No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	No Issues Reported	No Issues Reported
Odometer Check No indication of an odometer rollback.	No Issues Indicated	No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	No Issues Reported	No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires repair. Most recalls can be repaired free of charge.	No Recalls Reported	Recall Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

CARFAX Detailed History

Owner 1 Purchased: 2003



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Lease Vehicle 7,481 mi/yr

Date	Mileage	Source	Comments
11/03/2003	9	Mercedes-Benz of Danbury Danbury, CT 203-778-6333 mercedesbenzofdanbury.com 4.4 / 5.0 13 Verified Reviews	Vehicle serviced - Pre-delivery inspection completed - Vehicle washed/detailed
11/08/2003	20	Connecticut Motor Vehicle Dept.	Vehicle purchase reported
12/16/2003		Connecticut Motor Vehicle Dept. Roanoke, TX Title #027953823	Title issued or updated - First owner reported - Titled or registered as lease vehicle



Two states? Vehicle leasing companies often title a car in one state but register it to be driven in another.

		FC	ix 🌶
06/14/2004	4,287	Mercedes-Benz of Danbury Danbury, CT 203-778-6333 danbury.mercedescenter.com 4.4 / 5.0 13 Verified Reviews	Vehicle serviced - GPS/Navigation system checked - GPS/Navigation antenna replaced
08/20/2004		Mercedes-Benz of Danbury Danbury, CT 203-778-6333 danbury.mercedescenter.com	Vehicle serviced

		★ 4.4 / 5.0 13 Verified Reviews	
08/30/2004		Mercedes-Benz of Danbury Danbury, CT 203-778-6333 mercedesbenzofdanbury.com 4.4 / 5.0 13 Verified Reviews	Vehicle serviced
09/27/2004	7,560	Mercedes-Benz of Danbury Danbury, CT 203-778-6333 danbury.mercedescenter.com 4.4 / 5.0 13 Verified Reviews	Vehicle serviced - Interior trim checked - Internal transmission repaired - Brakes checked - Armrest replaced
07/11/2005	14,101	Mercedes-Benz of Danbury Danbury, CT 203-778-6333 danbury.mercedescenter.com 4.4 / 5.0 13 Verified Reviews	Vehicle serviced - Radio/sound system checked - Wheels checked - Computer(s) checked
01/09/2006	18,752	Mercedes-Benz of Danbury Danbury, CT 203-778-6333 danbury.mercedescenter.com 4.4 / 5.0 13 Verified Reviews	Vehicle serviced - Interior trim checked
05/21/2007	26,300	Mercedes-Benz of Danbury Danbury, CT 203-778-6333 danbury.mercedescenter.com	Vehicle serviced - Maintenance inspection completed - Seatbelts checked - Front brake pads replaced - Rear brake pads replaced - Cooling system checked - A/C system serviced - Exterior light bulb(s) replaced - Wiper(s) replaced - Wipers/washers checked - Fluids checked - Turn signal bulb(s) replaced - Rain sensor computer/module replaced
11/15/2008	37,611	Mercedes-Benz of Danbury Danbury, CT 203-778-6333 danbury.mercedescenter.com ★ 4.4 / 5.0 13 Verified Reviews	Vehicle serviced - Pre-delivery inspection completed
11/17/2008		Mercedes-Benz of Danbury Danbury, CT 203-778-6333 mercedesbenzofdanbury.com ★ 4.4 / 5.0 13 Verified Reviews	Vehicle sold
11/17/2008		Connecticut Motor Vehicle Dept.	Vehicle purchase reported
11/26/2008		Connecticut Motor Vehicle Dept. New Fairfield, CT	Registration issued or renewed - Vehicle color noted as Gray





Low mileage! This owner drove less than the industry average of 15,000 miles per vear.

Personal Vehicle 3,847 mi/yr

Date	Mileage	Source	Comments
01/22/2009)	Connecticut Motor Vehicle Dept. New Fairfield, CT Title #031463995	Title issued or updated - New owner reported
05/18/2009	40,563	Mercedes-Benz of Danbury Danbury, CT 203-778-6333 danbury.mercedescenter.com 4.4 / 5.0 13 Verified Reviews	Vehicle serviced - Recommended maintenance performed - GPS/Navigation module/computer checked - Oil and filter changed - Wheels checked - A/C system checked - Wiper(s) replaced - Console repaired - Front wiper blades/refills replaced
08/12/2009	42,125	Mercedes-Benz of Danbury Danbury, CT 203-778-6333 danbury.mercedescenter.com 4.4 / 5.0 13 Verified Reviews	Vehicle serviced - Battery/charging system checked - Radio/sound system checked
09/14/2009	42,656	Mercedes-Benz of Danbury Danbury, CT 203-778-6333 danbury.mercedescenter.com ★ 4.4 / 5.0 13 Verified Reviews	Vehicle serviced - Battery/charging system checked
10/30/2009	43,619	Mercedes-Benz of Danbury Danbury, CT 203-778-6333 mercedesbenzofdanbury.com ★ 4.4 / 5.0 13 Verified Reviews	Vehicle serviced - Body electrical system checked
11/16/2009	43,856	Mercedes-Benz of Danbury Danbury, CT 203-778-6333 mercedesbenzofdanbury.com 4.4 / 5.0 13 Verified Reviews	Vehicle serviced - Ashtray replaced - Lighter replaced/repaired - GPS/Navigation module/computer checked - Radio/sound system checked
07/16/2010	48,089	Mercedes-Benz of Danbury Danbury, CT 203-778-6333 danbury.mercedescenter.com 4.4 / 5.0 13 Verified Reviews	Vehicle serviced - Recommended maintenance performed - Maintenance inspection completed - Lower ball joint(s) replaced - Engine serviced - Brake fluid flushed/changed - Air filter replaced - Cabin air filter replaced/cleaned - Front brake rotor(s) resurfaced - Engine oil/fluid leak checked - Oil and filter changed - Engine checked - Door locks checked - Transfer case serviced - Front brake rotor(s) replaced - Front brake pads replaced - Transmission checked - Steering/suspension checked
04/30/2011	53,759	Mercedes-Benz of Danbury Danbury, CT 203-778-6333 danbury.mercedescenter.com 4.4 / 5.0 13 Verified Reviews	Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Brake light switch replaced - Oil and filter changed - Brakes checked
08/22/2011	57,084	Mercedes-Benz of Danbury	Vehicle serviced

		Danbury, CT 203-778-6333 danbury.mercedescenter.com 4.4 / 5.0 13 Verified Reviews	- Control arm(s) replaced - GPS/Navigation system checked - Steering/suspension checked
08/31/2011		Mercedes-Benz of Danbury Danbury, CT 203-778-6333 mercedesbenzofdanbury.com 4.4 / 5.0 13 Verified Reviews	Vehicle serviced - GPS/Navigation system checked - Steering/suspension checked
09/05/2011		Connecticut Motor Vehicle Dept. New Fairfield, CT	Registration issued or renewed - Vehicle color noted as Gray
12/31/2013	66,221	Mercedes-Benz of Cutler Bay Cutler Bay, FL 305-251-0345 mbcutlerbay.com	Vehicle serviced - Vehicle washed/detailed
12/16/2015	70,378	Mercedes-Benz of Cutler Bay Cutler Bay, FL 305-251-0345 mbcutlerbay.com	Vehicle serviced - Vehicle washed/detailed
12/27/2016	72,792	Mercedes-Benz of Cutler Bay Cutler Bay, FL 305-251-0345 mbcutlerbay.com	Vehicle serviced - Maintenance inspection completed - Vehicle washed/detailed - Front wiper blades/refills replaced
01/04/2019	77,651	Mercedes-Benz of Cutler Bay Cutler Bay, FL 305-251-0345 mbcutlerbay.com	Vehicle serviced - Vehicle washed/detailed - Four tires replaced
06/25/2020		Mercedes-Benz USA LLC	Manufacturer Safety recall issued - NHTSA #19V918 - Recall #2020040011 Recall - Safety Title/ Topic: - Sliding Roof Bonding MY: 2001-2011 Model(s): - Various models - Status: Remedy Available Click here or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall - Learn more about this recall

Description: Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 01-11 C-Class (203 platform), CLK-Class (209 platform), E-Class (211 platform) and CLS-Class (219 platform) vehicles, the bonding between the glass panel and the sliding roof frame might not meet specifications. In this case, the adhesion of the bonding could deteriorate gradually over time. If the bonding adhesion were to deteriorate, the durability requirements might not be met which could lead to a separation of the glass panel from the vehicle. A displaced panel could increase the risk of a potential crash or injury for other road users.

In this case, the adhesion of the bonding could deteriorate gradually over time. If the bonding adhesion were to deteriorate, the durability requirements might not be met which could lead to a separation of the glass panel from the vehicle. A displaced panel could increase the risk of a potential crash or injury for other road users.

Remedy: MBUSA will conduct a voluntary recall. An authorized Mercedes-Benz dealer will check the glass panel bonding on the affected vehicles and replace the sliding roof, as necessary.

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

When someone leases a car from a dealer, the dealer actually sells the vehicle to a leasing company. The leasing company then collects payments for the vehicle from the new owner for 24, 36, 48 or more months. A leasing company can be an independent car dealer or a car manufacturer.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform owners of car defects that have come to the manufacturer's attention. Recalls also suggest improvements that can be made to improve the safety of a particular vehicle. Most manufacturer recalls can be repaired at no cost to you.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



@CARFAXinc



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2021 CARFAX, Inc., a unit of IHS Markit Ltd. All rights reserved. 4/29/21 2:28:05 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2004 MERCEDES-BENZ E CLASS vehicle (VIN: WDBUH82J74X115138), which is based on information supplied to CARFAX and available as of 4/29/21 at 3:28 PM (EDT).

Date